


## Jogo sincronização BMW/Land Rover Ref.: 1501



### Aplicações:

**BMW** 118d E87(03-07); 120d E87 (03-07); 318d/td E46/E90/91 (00-07); 320d/cd E46/E90/91 (97-07); 325d E90/91/92/93 (06-08); 330d/xd/cd E46/E90/91/92/93 (98-08); 335d E90/91/92 (06-08); 520d E39/E60/61 (99-08); 525d/xd E39/E60/61 (99-08); 530d/xd E39/E60/61 (98-08); 535d E60/61 (04-08); 635d E63/61 (04-08); 730d/Ld E38/E65/66 (98-08); X3 2.0d E83 (03-07); X3 3.0d/sd E83 (03-08); X5 3.0d E53/E70 (00-08); **Land Rover** Freelander (00-06); **Rover** 75 2.0D

### Motores:

M47 / M57, M47TU / M57TU, M47T2 / M57T2

### Códigos de motor

20 4D 1, 20 4D 4, 25 6D 1, 25 6D 2, 30 6D 1, 30 6D 2, 30 6D 3, 30 6D 4 ,30 6D 5.

Peça	Descrição	Código OEM
<b>A</b>	<b>Ferramenta bloqueio árvore de cames</b>	<b>11 6 320</b>
<b>B</b>	<b>Pino tensor (2)</b>	<b>11 3 340</b>
<b>C</b>	Grampo de bloqueio	<b>11 6 322</b>
<b>D</b>	Pino de ajuste da cambota	<b>11 2 300</b>

Modo de uso:

