

FERRAMENTA SINCRONIZAÇÃO FORD 1.8-TDDI/TDCI REF.: 1518



Motores:

1.8D TDCi: BHPA, F9DA, F9DB, FFBA, FFDA, FFWA, HCPA, HCPB, KHBA, KKDA, KKDB, P7PA, P9PA, P9PB, QYBA, QYWA, R2PA, R3PA, RWPA, RWPC

1.8D TDCi ECONetic: KHBA

1.8D Tdi: BHDA, BHDB, BHPA, C9DA, C9DB, C9DC

1.8D Turbo: C9DC, RTN, RTP, RTQ

Modelos:

C-MAX (07-10), Courier (00-02), Fiesta (00-02), Focus (98-11), Focus C-MAX (03-07), Galaxy (06-10), Mondeo (07-10) S-MAX, (06-10), Tourneo Connect (02-12), Transit Connect (02-12)



Item	Descrição	Código OEM
A	Pino localização da cambota	303-193/21-104
B	Ferramenta de bloqueio do volante	303-393, 21-168
C	Ferramenta de alinhamento da tampa dianteira	303-652 , 21-230
D	Ferramenta bloqueio da polia da bomba injetora	23-067/303-095
E	Bloqueio correia da árvore de cames	21-162B/303-367 303-376
F	Pino de bloqueio da bomba injetora	